

## ECS/EMD Configuration Change Request

Page 1 of

Page(s)

1. Originator Maryellen Corbett	2. Log Date: 02/02/04	3. CCR #: 04-0078	4. Rev: —	5. Tel: 301 925-0703	6. Rm #: 3104B	7. Org. COTS
8. CCR Title: Baseline Update February 2004 (#23)						
9. Originator Signature/Date Maryellen Corbett /s/ 02/02/04			10. Class II	11. Type: CCR	12. Need Date: 02/15/2004	
13. CCR Sponsor Signature/Date Pamela Johnson /s/ 02/02/04			14. Category of Change: Update ECS/EMD Baseline Doc		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): See attached page			17. Schedule Impact:		18. CI(s) Affected:	
19. Release Affected by this Change: 6A		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) Some baseline inconsistencies have been identified. These may involve baseline updates and/or installation/removal of COTS products to resolve identified baseline inconsistencies.						
24. Proposed Solution: (use additional sheets if necessary) Provide baseline red-lines and/or ECOs to resolve identified discrepancies. Attached sheet provides summary of baseline and system administration changes. These changes are also included in the ECO instructions for resolution of identified baseline discrepancies.						
25. Alternate Solution: (use additional sheets if necessary) Accept an inconsistent baseline and installations						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inconsistent baseline and installations						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input checked="" type="checkbox"/> PVC <input checked="" type="checkbox"/> VATC <input type="checkbox"/> EDC <input type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. SCDV CCB Chair (Sign/Date): Byron V. Peters /s/ 02/05/04			Disposition: <span style="border: 1px solid red; color: red;">Approved</span> App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. EDF CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

# ADDITIONAL SHEET

**CCR #:** 04-0078    **Rev:—**    **Originator:** Maryellen Corbett

**Telephone:**                      **Office:**

**Title of Change:** Baseline Update February 2004 (#23)

## CM Documents:

920-TDP-002: PVC HW/SW Map  
920-TDV-014: VATC Patch Map  
920-TDN-014: NSIDC Patch Map  
911-TDA-005: Release B SGI IRIX 6.5.17 Patch List  
910-TDA-003: COTS Version Map

## Baseline Documentation updates ONLY:

1. Add SGI patches #4704 and 4511 to the patch baseline of t1aqq02. Patches are installed. Patches required when compilers installed. Compilers are currently installed.
2. Add Netscape Communicator 7.0 to the baseline of the following PVC machines. Software is currently configured to run on these machines.
  - a. p0tes03
  - b. p2dms01
  - c. p2ins02
3. Add Remedy\_aruser\_Patch ##1105 to the baseline of t1ins02. Patch is currently correctly installed.
4. Add SGI IRIX 6.5.17 patch #4781 (QLogic Fibrechannel and disk update for 6.5.15, 6.5.16, 6.5.17) to all SGI 6.5.17 hosts. Patch installs on all hosts and is not hardware dependent as originally identified.
5. Add SGI Patch #4848 (ef driver limiting packets per second) to the patch baseline of n0spg03 (IRIX 6.5.17 patch). Patch is currently installed.
6. Add SGI Patch #4903 (System Controller Firmware/Software Updates for IRIX 6.5.12-6.5.18) to the patch baseline of n0spg03 (IRIX 6.5.17 patch). Patch is currently installed and was identified to be installed on this host, hardware configuration permitting.
7. Update the path for Legato Networker 7.1 Cl. The path for the client and server should be /usr/ecs/OPS/COTS/nsr.

## Infrastructure ECOs/System Administration Activities:

1. Upgrade SGI compilers to the current baseline version, 7.3.1.3, on the following VATC Hosts, using the IRIX 6.5.17 PSR installation (compiler install was bundled with this delivery). Hosts are currently baselined for this version.
  - a. t1dpg06
  - b. t1acg04
  - c. t1drg03
  - d. t1spg03
2. Remove obsolete version of NCDWare (4.1.141 ) from the following directories on p2pls01:
  - a. /data/tftpboot/ncd/Xncd.4.1.141
  - b. /tftpboot/ncd/Xncd.4.1.141
3. Remove Tripwire 1.2 and associated patches from t1pls02 in the /etc/tripwire-1.2 directory.